

50 30 00  
032  
9/24/88  
75160

PRELIMINARY ASSESSMENT  
NARRATIVE

Re: Granville Solvents  
Licking County  
OHD004495412

August 30, 1985

Granville Solvents, Inc. is located on Palmer Lane, Granville, Ohio, adjacent to and west of State Route 16 and north of the Penn Central Railroad right of way. The company began in 1953 as a petroleum solvent storage, packaging, blending and distribution facility for industrial trade. It moved to its present location in 1958 where it continued the described activities until mid-1980. The operation then changed to a solvent reclamation/recycling facility and according to the 103(c) notification (June 11, 1981) handles methylene chloride, tetrachloroethylene, 1,1,1-trichloroethane, trichloroethene, trichlorofluoromethane and methanol.

Granville Solvents Part A permit application was approved December 17, 1981 with a Part B permit application is currently under review by the Ohio Hazardous Waste Facility Board. Presently, the facility is regulated under RCRA and no portion of the property is known to have been used as an unregulated hazardous waste site.

Until closure or abandonment of the facility occurs additional actions pursuant to CERCLA and the National Contingency Plan (see 40 CFR, Part 300) are inappropriate. Ohio EPA will continue to monitor the facility under RCRA to ensure permit compliance. (Low State priority, no FIT priority at this time.)

Submitted By:

Reviewed By:

William M. Schneider  
Division of Solid & Hazardous  
Waste Management  
Central District Office

Steven A. Rath, P.E., Unit Supervisor  
Division of Solid & Hazardous  
Waste Management  
Central District Office

WMS/sc

1034T



POTENTIAL HAZARDOUS WASTE SITE  
PRELIMINARY ASSESSMENT  
PART 1 - SITE INFORMATION AND ASSESSMENT

I. IDENTIFICATION

01 STATE 02 SITE NUMBER  
OH D004985912

II. SITE NAME AND LOCATION

01 SITE NAME (Legal, common, or descriptive name of site) Granville Solvents, Inc.	02 STREET, ROUTE NO., OR SPECIFIC LOCATION IDENTIFIER Palmer Lane, P.O. Box 300
03 CITY Granville	04 STATE 05 ZIP CODE 06 COUNTY OH 43023 Licking
07 COUNTY CODE 089	08 COND DIST OH-17
09 COORDINATES LATITUDE	LONGITUDE

10 DIRECTIONS TO SITE (Starting from nearest public road)

See Attached Map

III. RESPONSIBLE PARTIES

01 OWNER (If known)	02 STREET (Business, mailing, residential) Same as above
03 CITY Same as above	04 STATE 05 ZIP CODE 06 TELEPHONE NUMBER 614 587-0079
07 OPERATOR (If known and different from owner)	08 STREET (Business, mailing, residential)
09 CITY	10 STATE 11 ZIP CODE 12 TELEPHONE NUMBER ( )

13 TYPE OF OWNERSHIP (Check one)

☒ A. PRIVATE ☐ B. FEDERAL ☐ C. STATE ☐ D. COUNTY ☐ E. MUNICIPAL  
☐ F. OTHER: (Specify) ☐ G. UNKNOWN

14 OWNER/OPERATOR NOTIFICATION ON FILE (Check all that apply)

☒ A. RCRA 3001 DATE RECEIVED: 12, 17, 81 ☒ B. UNCONTROLLED WASTE SITE (CERCLA 103 H) DATE RECEIVED: 6, 9, 81 ☐ C. NONE

IV. CHARACTERIZATION OF POTENTIAL HAZARD

01 ON SITE INSPECTION YES DATE 5, 29, 85 (Last RCRA Inspection)	02 BY (Check all that apply) <input type="checkbox"/> A. EPA <input type="checkbox"/> B. EPA CONTRACTOR <input checked="" type="checkbox"/> C. STATE <input type="checkbox"/> D. OTHER CONTRACTOR <input type="checkbox"/> E. LOCAL HEALTH OFFICIAL <input type="checkbox"/> F. OTHER: (Specify)
03 SITE STATUS (Check one) <input checked="" type="checkbox"/> A. ACTIVE <input type="checkbox"/> B. INACTIVE <input type="checkbox"/> C. UNKNOWN	04 YEARS OF OPERATION 1950 present (1985) UNKNOWN

04 DESCRIPTION OF SUBSTANCES POSSIBLY PRESENT, KNOWN, OR ALLEGED

see part 2.

05 DESCRIPTION OF POTENTIAL HAZARD TO ENVIRONMENT AND/OR POPULATION

Facility located on floodplain; potential for spills to runoff to stream or into groundwater.


V. PRIORITY ASSESSMENT

01 PRIORITY FOR INSPECTION (Check one. If high or medium is checked, complete Part 2 - Waste information and Part 3 - Description of Hazardous Conditions and Remedies)

☐ A. HIGH (Inspection required promptly) ☐ B. MEDIUM (Inspection required) ☐ C. LOW (Inspect on site available soon) ☐ D. NONE (No further action needed. Complete current inspection form)

VI. INFORMATION AVAILABLE FROM

01 CONTACT William M. Schneider	02 CF (Agency-Organization) Ohio EPA	03 TELEPHONE NUMBER 614 462-8394
04 PERSON RESPONSIBLE FOR ASSESSMENT Same	05 AGENCY Ohio EPA	06 ORGANIZATION ( )
07 TELEPHONE NUMBER ( )	08 DATE 9, 11, 85	



## 03 WASTE CHARACTERISTICS (CHECK ALL THAT APPLY)


### III. WASTE TYPE

IV. HAZARDOUS SUBSTANCES (See ADDRESS OF THE ISSUING STATE CAL NUMBER)


## V. FEEDSTOCKS / See Appendix for CAS Numbers

VL SOURCES OF INFORMATION (Cite specific references, e.g., state doc. system analysis, reports)

EPA FORM 2070-12 (7-81)



Ware house: Metal frame,  
 sheet metal skin  
 2400 FT<sup>2</sup>  
 Still/Still House: Electric  
 Hook/Sheet Metal  
 1000 FT<sup>2</sup>



Granite Slabs, Inc.  
 1000 FT<sup>2</sup>  
 1000 FT<sup>2</sup>  
 1000 FT<sup>2</sup>

# EPA Notification of Hazardous Waste Site

United States  
Environmental Protection  
Agency  
Washington DC 20460

This initial notification information is required by Section 103(c) of the Comprehensive Environmental Response, Compensation, and Liability Act of 1980 and must be mailed by June 9, 1981.

Please type or print in ink. If you need additional space, use separate sheets of paper. Indicate the letter of the item which applies.

OH #162

810609

OH5-000-001-159

## A Person Required to Notify:

Enter the name and address of the person or organization required to notify.

Name Granville Solvents, Inc.

Street Palmer Lane, P.O. Box 300

City Granville

State Ohio

Zip Code 43023

## B Site Location:

Enter the common name (if known) and actual location of the site.

Name of Site Granville Solvents, Inc.

Street Palmer Lane, P.O. Box 300

City Granville

County Licking

State Ohio

Zip Code 43023

## C Person to Contact:

Enter the name, title (if applicable), and business telephone number of the person to contact regarding information submitted on this form.

Name (Last, First and Title) Reeb, John E. President/Manager

Phone 614-587-0079

## D Dates of Waste Handling:

Enter the years that you estimate waste treatment, storage, or disposal began and ended at the site.

From (Year) 1980

To (Year) Present

1981

## E Waste Type: Choose the option you prefer to complete

Option 1: Select general waste types and source categories. If you do not know the general waste types or sources, you are encouraged to describe the site in Item I—Description of Site.

### General Type of Waste:

Place an X in the appropriate boxes. The categories listed overlap. Check each applicable category.

1. ☐ Organics
2. ☐ Inorganics
3. ☐ Solvents
4. ☐ Pesticides
5. ☐ Heavy metals
6. ☐ Acids
7. ☐ Bases
8. ☐ PCBs
9. ☐ Mixed Municipal Waste
10. ☐ Unknown
11. ☐ Other (Specify)

### Source of Waste:

Place an X in the appropriate boxes.

1. ☐ Mining
2. ☐ Construction
3. ☐ Textiles
4. ☐ Fertilizer
5. ☐ Paper/Printing
6. ☐ Leather Tanning
7. ☐ Iron/Steel Foundry
8. ☐ Chemical, General
9. ☐ Plating/Polishing
10. ☐ Military/Ammunition
11. ☐ Electrical Conductors
12. ☐ Transformers
13. ☐ Utility Companies
14. ☐ Sanitary/Refuse
15. ☐ Photofinish
16. ☐ Lab/Hospital
17. ☐ Unknown
18. ☐ Other (Specify)

Option 2: This option is available to persons familiar with the Resource Conservation and Recovery Act (RCRA) Section 3001 regulations (40 CFR Part 261).

### Specific Type of Waste:

EPA has assigned a four-digit number to each hazardous waste listed in the regulations under Section 3001 of RCRA. Enter the appropriate four-digit number in the boxes provided. A copy of the list of hazardous wastes and codes can be obtained by contacting the EPA Region serving the State in which the site is located.

U080	<u>hexachloromethane</u>	
U210	<u>tetrachloroethylene</u>	
U226	<u>trichloroethylene</u>	
U228	<u>trichloroethylene</u>	
U229	<u>trichloromono-fluoromethane</u>	
U154	<u>Methanol</u>	

000732 JUN -9 81

JUN 11 1981

**F Waste Quantity:**

Place an X in the appropriate boxes to indicate the facility types found at the site.

In the "total facility waste amount" space give the estimated combined quantity (volume) of hazardous wastes at the site using cubic feet or gallons.

In the "total facility area" space, give the estimated area size which the facilities occupy using square feet or acres.

**Facility Type**

1. ☐ Piles
2. ☐ Land Treatment
3. ☐ Landfill
4. ☒ Tanks
5. ☐ Impoundment
6. ☐ Underground Injection
7. ☒ Drums, Above Ground
8. ☐ Drums, Below Ground
9. ☐ Other (Specify) \_\_\_\_\_

**Total Facility Waste Amount**

cubic feet

gallons 55,000 in drums, 50,000 in tanks**Total Facility Area**

square feet

acres approx. 2**G Known, Suspected or Likely Releases to the Environment:**

Place an X in the appropriate boxes to indicate any known, suspected, or likely releases of wastes to the environment.

☐ Known ☐ Suspected ☐ Likely ☒ None

Note: Items H and I are optional. Completing these items will assist EPA and State and local governments in locating and assessing hazardous waste sites. Although completing the items is not required, you are encouraged to do so.

**H Sketch Map of Site Location: (Optional)**

Sketch a map showing streets, highways, routes or other prominent landmarks near the site. Place an X on the map to indicate the site location. Draw an arrow showing the direction north. You may substitute a publishing map showing the site location.

Please find enclosed information sent to USEPA in Hazardous Waste Permit Application Consolidated Permits Program Form 1 and Form 3 submitted October 28, 1980 under our EPA ID # OHDO04495412 as a Solvent Reclaim.

**I Description of Site: (Optional)**

Describe the history and present conditions of the site. Give directions to the site and describe any nearby wells, springs, lakes, or housing. Include such information as how waste was disposed and where the waste came from. Provide any other information or comments which may help describe the site conditions.

Until mid-1980, Granville Solvnets, Inc. was engaged in petroleum solvents storage, packaging, blending, and distribution for the industrial trade. At that time a decision to change operations because of declining business to solvent reclamation/recycling. As per the enclosed maps and diagrams, a small river runs 50 yards to the south of the plant; municipal water wells exist  $\frac{1}{4}$  of a mile west of the facility upstream; nearest housing is 50 yards north across a municipal street. Waste sited at the facility falls in the general classification of "chlorinated hydrocarbon solvents" which are stored in both drums (inside and outside our building) and underground storage. The plant site is located on a south-facing slope which is bordered on the south by an abandoned rail siding. Soil composition is generally clay over gravel.

**J Signature and Title:**

The person or authorized representative (such as plant managers, superintendents, trustees or attorneys) of persons required to notify must sign the form and provide a mailing address (if different than address in item A). For other persons providing notification, the signature is optional. Check the boxes which best describe the relationship to the site of the person required to notify. If you are not required to notify check "Other".

Name John E. ReebStreet Palmer Lane, P.O. Box 300City GranvilleState Ohio Zip Code 43023Signature John E. ReebDate June 8, 1981

- ☒ Owner, Present  
☐ Owner, Past  
☐ Transporter  
☒ Operator, Present  
☐ Operator, Past  
☐ Other